BALL JANIK LLP

ATTORNEYS

1455 F STREET, NW, SUITE 225
WASHINGTON, D.C. 20005
www.balljanik.com
TELEPHONE 202-638-3307
FACSIMILE 202-783-6947

RECORDATION NO. 25535 FILED

APR 05 '05 3-33 PM

SURFACE TRANSPORTATION BOARD

LOUIS E. GITOMER@dc.bjllp.com
OF COUNSEL
(202) 466-6532

April 5, 2005

Honorable Vernon A. Williams
Secretary
Surface Transportation Board
Washington, DC 20423

Dear Secretary Williams:

I have enclosed two original copies of the document described below, to be recorded pursuant to 49 U.S.C. § 11301.

The document is a Memorandum of Lease Agreement, a primary document, dated as of March 28, 2005. We request that this document be given the next available Recordation Number.

The names and addresses of the parties to the Memorandum of Lease Agreement are:

Lessor:

LaSalle National Leasing Corporation
One West Pennsylvania Avenue, Suite 1000
Towson, MD 21204

Lessee:

Degussa Engineered Carbons, L.P.
379 Interpace Parkway
Parsippany, NJ 07054-8083

A description of the equipment covered by the Memorandum of Lease Agreement consists of 440 covered hopper cars numbered DCBX 2001-2055, inclusive, and 2057-2100, inclusive, and ECQX 4708, 4711, 4716, 4724-4726, inclusive, 4774-4779, inclusive, 4781, 4783-4800, inclusive, 4802-4853, inclusive, 5116, 5117, 8009, 8017, 8018, 8020, 8021, 8023-8025, inclusive, 8029, 8030, 8032, 8033, 8035, 8036, 8039, 8044, 8047, 8048, 8054-8056, 8061, 8063, 8064, 8066, 8067, 8070, 8071, 8078, 8079, 8083, 8087, 8090, 8091, 8093, 8095, 8098, 8099, 41381, 41383, 41387-41392, inclusive, 41394-41396, inclusive, 41398-41408, inclusive, 41410-41423, inclusive, 57424-57434, inclusive, 57436, 57437, 57439, 57440, 57442-57445,

inclusive, 57447-57557, inclusive, 57559-57571, inclusive, 72701-72736, inclusive, and 72738-72741, inclusive.

A fee of $ 32.00 is enclosed. Please return one original to:

Louis E. Gitomer
Of Counsel
Ball Janik LLP
Suite 225
1455 F Street, N.W.
Washington, DC 20005

A short summary of the document to appear in the index follows: a Memorandum of Lease Agreement between LaSalle National Leasing Corporation, One West Pennsylvania Avenue, Suite 1000, Towson, MD 21204, and Degussa Engineered Carbons, L.P., 379 Interpace Parkway, Parsippany, NJ 07054-8083, covering 440 covered hopper cars numbered DCBX 2001-2055, inclusive, and 2057-2100, inclusive, and ECQX 4708, 4711, 4716, 4724-4726, inclusive, 4774-4779, inclusive, 4781, 4783-4800, inclusive, 4802-4853, inclusive, 5116, 5117, 8009, 8017, 8018, 8020, 8021, 8023-8025, inclusive, 8029, 8030, 8032, 8033, 8035, 8036, 8039, 8044, 8047, 8048, 8054-8056, 8061, 8063, 8064, 8066, 8067, 8070, 8071, 8078, 8079, 8083, 8087, 8090, 8091, 8093, 8095, 8098, 8099, 41381, 41383, 41387-41392, inclusive, 41394-41396, inclusive, 41398-41408, inclusive, 41410-41423, inclusive, 57424-57434, inclusive, 57436, 57437, 57439, 57440, 57442-57445, inclusive, 57447-57557, inclusive, 57559-57571, inclusive, 72701-72736, inclusive, and 72738-72741, inclusive.

Very Truly Yours,

Louis E. Gitomer

Enclosures

RECORDATION NO. 25535 FILED

APR 05 '05 3-33 PM

SURFACE TRANSPORTATION BOARD

MEMORANDUM OF LEASE AGREEMENT

dated as of March 28, 2005

between

DEGUSSA ENGINEERED CARBONS, L.P.,
as Lessee,

and

LASALLE NATIONAL LEASING CORPORATION,
as Lessor

FILED WITH THE SURFACE TRANSPORTATION BOARD
PURSUANT TO 49 U.S.C. § 11301
on _____ __, 2005 at __:__ _.m.

MEMORANDUM OF LEASE AGREEMENT

THIS MEMORANDUM OF LEASE AGREEMENT is made and entered into as of March 28, 2005, by and between LASALLE NATIONAL LEASING CORPORATION ("Lessor") and DEGUSSA ENGINEERED CARBONS, L.P. ("Lessee"), with reference to the following:

1. Lessor has agreed to purchase and lease to Lessee, and Lessee has agreed to lease from Lessor, those certain Units described on Exhibit No. 1 attached hereto.

   All of such Units are more fully described in that certain Rail Equipment Lease Agreement dated as of march 28, 2005, and Schedule No. A-1, B-1,and B-2 thereto and incorporating the terms thereof, dated as of March 31, 2005 (together with all of the riders, schedules and other attachments thereto, collectively, the "Lease"), each between Lessor and Lessee.

2. The Lease shall be effective as of the date hereof and shall be subject to the term specified in the Lease, and any extension of such term to the extent provided for in the Lease.

This Memorandum of Lease Agreement may be executed in any number of counterparts, each executed counterpart constituting an original but all together only one Memorandum of Lease Agreement.

[REMAINDER OF PAGE INTENTIONALLY LEFT BLANK]

IN WITNESS WHEREOF, the parties hereto have executed or caused this Memorandum of Lease Agreement to be executed as of the date first above written.

LASALLE NATIONAL LEASING CORPORATION

By: _____
Name: TERRI J. PRESTON
Title: VICE PRESIDENT

DEGUSSA ENGINEERED CARBONS, L.P.

By: DEGUSSA ENGINEERED CARBONS, L.L.C., its General Partner

By: _____
Name: James V. Hickey
Title: VP + CFO

STATE OF MARYLAND)
) ss.
COUNTY OF BALTIMORE)

On this 1 day of April, 2005, before me appeared Terri J. Preston the person who signed this instrument, who acknowledged that (s)he is the Vice President of LASALLE NATIONAL LEASING CORPORATION and that, being duly authorized, (s)he signed such instrument as a free act on behalf of said corporation.

[Seal]

DANA L. McGURK NOTARY PUBLIC BALTIMORE COUNTY, MARYLAND

_____
Notary Public

My commission expires:
November 1, 2007

AJM 570695.1 2/24/2005 12:04 PM

STATE OF NEW JERSEY)
) ss.
COUNTY OF MORRIS)

On this 24th day of MARCH, 2005, before me appeared JAMES V. HACKEY, the person who signed this instrument, who acknowledged that (s)he is the VP+CFO of DEGUSSA ENGINEERED CARBONS, L.L.C. and that, being duly authorized, (s)he signed such instrument as a free act on behalf of said corporation.

[Seal]

Nancy A. Montesano
Notary Public

My commission expires:
Oct 3, 2009

NANCY A. MONTESANO
NOTARY PUBLIC OF NEW JERSEY
Commission Expires 10/3/2009

EXHIBIT NO. 1
TO MEMORANDUM OF LEASE AGREEMENT

DESCRIPTION OF RAILCARS AND REPORTING MARKS

	CAR NUMBER	CAPACITY	TARE WT	YEAR
BRIG	DCBX002001	4727	56,200	1996
BRIG	DCBX002002	4727	56,200	1996
UNIT	DCBX002003	4727	55,900	1996
KOSM	DCBX002004	4727	55,800	1996
KOSM	DCBX002005	4727	55,900	1996
UNIT	DCBX002006	4727	55,600	1996
KOSM	DCBX002007	4727	55,800	1996
UNIT	DCBX002008	4727	55,700	1996
KOSM	DCBX002009	4727	55,900	1996
KOSM	DCBX002010	4727	55,900	1996
KOSM	DCBX002011	4727	56,000	1996
BRIG	DCBX002012	4727	55,900	1996
KOSM	DCBX002013	4727	56,300	1996
BRIG	DCBX002014	4727	56,300	1996
KOSM	DCBX002015	4727	55,900	1996
BRIG	DCBX002016	4727	56,000	1996
BRIG	DCBX002017	4727	55,900	1996
ECHO	DCBX002018	4727	56,300	1996
UNIT	DCBX002019	4727	56,300	1996
KOSM	DCBX002020	4727	56,200	1996
KOSM	DCBX002021	4727	55,900	1996
BRIG	DCBX002022	4727	56,300	1996
UNIT	DCBX002023	4727	56,000	1996
KOSM	DCBX002024	4727	56,000	1996
UNIT	DCBX002025	4727	55,800	1996
BRIG	DCBX002026	4727	56,100	1996
KOSM	DCBX002027	4727	56,200	1996
KOSM	DCBX002028	4727	55,800	1996
KOSM	DCBX002029	4727	56,000	1996
UNIT	DCBX002030	4727	55,900	1996
KOSM	DCBX002031	4727	55,900	1996
UNIT	DCBX002032	4727	55,800	1996
BRIG	DCBX002033	4727	55,700	1996
KOSM	DCBX002034	4727	56,200	1996
UNIT	DCBX002035	4727	56,400	1996
UNIT	DCBX002036	4727	56,200	1996
BRIG	DCBX002037	4727	56,100	1996
UNIT	DCBX002038	4727	56,200	1996
KOSM	DCBX002039	4727	56,300	1996
UNIT	DCBX002040	4727	56,200	1996
KOSM	DCBX002041	4727	56,300	1996
KOSM	DCBX002042	4727	56,300	1996

KOSM	DCBX002043	4727	55,900	1996
KOSM	DCBX002044	4727	55,800	1996
BRIG	DCBX002045	4727	56,300	1996
BRIG	DCBX002046	4727	56,000	1996
KOSM	DCBX002047	4727	55,800	1996
BRIG	DCBX002048	4727	55,800	1996
KOSM	DCBX002049	4727	56,200	1996
BRIG	DCBX002050	4727	56,200	1996
BRIG	DCBX002051	4727	55,900	1996
BRIG	DCBX002052	4727	56,200	1996
KOSM	DCBX002053	4727	56,000	1996
UNIT	DCBX002054	4727	56,200	1996
KOSM	DCBX002055	4727	56,200	1996
UNIT	DCBX002057	4727	56,000	1996
KOSM	DCBX002058	4727	56,100	1996
KOSM	DCBX002059	4727	56,000	1996
KOSM	DCBX002060	4727	55,700	1996
UNIT	DCBX002061	4727	55,800	1996
KOSM	DCBX002062	4727	55,900	1996
UNIT	DCBX002063	4727	55,900	1996
BRIG	DCBX002064	4727	56,100	1996
BRIG	DCBX002065	4727	56,700	1996
BRIG	DCBX002066	4727	55,900	1996
BRIG	DCBX002067	4727	56,000	1996
KOSM	DCBX002068	4727	56,000	1996
KOSM	DCBX002069	4727	55,900	1996
KOSM	DCBX002070	4727	55,900	1996
BRIG	DCBX002071	4727	55,800	1996
BRIG	DCBX002072	4727	55,800	1996
BRIG	DCBX002073	4727	55,900	1996
BRIG	DCBX002074	4727	55,900	1996
BRIG	DCBX002075	4727	56,100	1996
BRIG	DCBX002076	4727	55,700	1996
KOSM	DCBX002077	4727	55,900	1996
BRIG	DCBX002078	4727	55,900	1996
SHOP	DCBX002079	4727	55,900	1996
UNIT	DCBX002080	4727	56,100	1996
UNIT	DCBX002081	4727	56,200	1996
UNIT	DCBX002082	4727	55,900	1996
KOSM	DCBX002083	4727	56,000	1996
KOSM	DCBX002084	4727	56,000	1996
BRIG	DCBX002085	4727	55,700	1996
UNIT	DCBX002086	4727	56,000	1996
KOSM	DCBX002087	4727	55,900	1996
UNIT	DCBX002088	4727	56,100	1996
BORG	DCBX002089	4727	56,100	1996
KOSM	DCBX002090	4727	56,000	1996
UNIT	DCBX002091	4727	55,800	1996
KOSM	DCBX002092	4727	55,700	1996

BRIG	DCBX002093	4727	55,900	1996
UNIT	DCBX002094	4727	55,800	1996
KOSM	DCBX002095	4727	56,000	1996
KOSM	DCBX002096	4727	55,600	1996
BRIG	DCBX002097	4727	55,700	1996
BRIG	DCBX002098	4727	55,800	1996
KOSM	DCBX002099	4727	55,800	1996
BRIG	DCBX002100	4727	55,900	1996
ECHO	ECQX004708	4700	62,800	1965
BORG	ECQX004711	4700	62,700	1965
KOSM	ECQX004716	4727	61,800	1965
KOSM	ECQX004724	4727	62,500	1965
ECHO	ECQX004725	4727	62,100	1965
BORG	ECQX004726	4700	64,400	1965
BORG	ECQX004774	4700	58,500	1967
ECHO	ECQX004775	4700	58,200	1967
ECHO	ECQX004776	4700	58,200	1967
UNIT	ECQX004777	4700	58,400	1967
ECHO	ECQX004778	4700	59,100	1967
UNIT	ECQX004779	4700	58,500	1967
ECHO	ECQX004781	4700	58,400	1967
ECHO	ECQX004783	4700	57,800	1967
ECHO	ECQX004784	4700	58,300	1967
KOSM	ECQX004785	4700	58,200	1967
ECHO	ECQX004786	4700	60,000	1967
ECHO	ECQX004787	4700	58,300	1967
ECHO	ECQX004788	4700	58,600	1967
BRIG	ECQX004789	4700	58,600	1967
ECHO	ECQX004790	4700	58,100	1967
UNIT	ECQX004791	4700	58,400	1967
ECHO	ECQX004792	4700	58,300	1967
UNIT	ECQX004793	4700	58,900	1967
ECHO	ECQX004794	4700	58,400	1967
BORG	ECQX004795	4700	58,500	1967
BORG	ECQX004796	4700	58,300	1967
ECHO	ECQX004797	4700	57,600	1967
UNIT	ECQX004798	4700	58,200	1967
UNIT	ECQX004799	4700	57,600	1967
ECHO	ECQX004800	4800	58,500	1967
ECHO	ECQX004802	4800	56,400	1967
BORG	ECQX004803	4800	58,500	1967
ECHO	ECQX004804	4800	58,600	1967
ECHO	ECQX004805	4800	58,300	1967
ECHO	ECQX004806	4800	57,700	1967
ECHO	ECQX004807	4800	58,500	1967
ECHO	ECQX004808	4800	58,200	1967
BORG	ECQX004809	4800	58,900	1967
ECHO	ECQX004810	4800	58,200	1967
ECHO	ECQX004811	4800	58,000	1967

ECHO	ECQX004812	4800	59,000	1967
BRIG	ECQX004813	4800	58,000	1967
ECHO	ECQX004814	4800	58,400	1967
brig	ECQX004815	4800	58,100	1967
BORG	ECQX004816	4800	58,400	1967
ECHO	ECQX004817	4800	58,500	1967
KOSM	ECQX004818	4800	58,900	1967
UNIT	ECQX004819	4800	58,500	1967
ECHO	ECQX004820	4800	58,300	1967
BORG	ECQX004821	4800	58,600	1967
ECHO	ECQX004822	4800	58,300	1967
ECHO	ECQX004823	4800	58,100	1967
ECHO	ECQX004824	4800	58,200	1967
ECHO	ECQX004825	4800	58,000	1967
ECHO	ECQX004826	4800	58,100	1967
ECHO	ECQX004827	4800	58,200	1967
ECHO	ECQX004828	4800	58,100	1967
ECHO	ECQX004829	4800	58,600	1967
UNIT	ECQX004830	4800	57,600	1967
ECHO	ECQX004831	4800	58,300	1967
ECHO	ECQX004832	4800	58,400	1967
ECHO	ECQX004833	4800	58,400	1967
ECHO	ECQX004834	4800	59,300	1967
BORG	ECQX004836	4800	58,400	1967
ECHO	ECQX004837	4800	57,900	1967
ECHO	ECQX004838	4800	58,200	1967
ECHO	ECQX004839	4800	60,500	1967
ECHO	ECQX004840	4800	58,300	1967
BORG	ECQX004841	4800	58,000	1967
ECHO	ECQX004842	4800	58,200	1967
ECHO	ECQX004843	4800	58,100	1967
BRIG	ECQX004844	4800	58,300	1967
KOSM	ECQX004845	4800	58,200	1967
ECHO	ECQX004846	4800	57,900	1967
KOSM	ECQX004847	4800	57,600	1967
ECHO	ECQX004848	4800	58,400	1967
ECHO	ECQX004849	4800	57,700	1967
BRIG	ECQX004850	4800	58,200	1967
ECHO	ECQX004851	4800	58,000	1967
ECHO	ECQX004852	4800	57,700	1967
BORG	ECQX004853	4800	57,700	1967
shop	ECQX005116	5700	61,000	1975
ECHO	ECQX005117	5700	60,800	1975
ECHO	ECQX008009	5700	61,300	1973
KOSM	ECQX008017	5700	61,100	1975
UNIT	ECQX008018	5700	60,110	1975
UNIT	ECQX008020	5700	61,100	1975
ECHO	ECQX008021	5700	61,200	1975
UNIT	ECQX008023	5700	61,100	1975

ECHO	ECQX008024	5700	61,100	1975
unit	ECQX008025	5700	61,200	1975
BORG	ECQX008029	5700	61,100	1975
UNIT	ECQX008030	5700	58,400	1977
ECHO	ECQX008032	5700	58,200	1977
UNIT	ECQX008033	5700	58,300	1977
ECHO	ECQX008035	5700	58,200	1977
ECHO	ECQX008036	5700	58,100	1977
UNIT	ECQX008039	5700	58,400	1977
ECHO	ECQX008044	5700	58,300	1977
ECHO	ECQX008047	5700	58,300	1977
UNIT	ECQX008048	5700	58,300	1977
KOSM	ECQX008054	5700	58,300	1977
UNIT	ECQX008055	5700	58,100	1977
ECHO	ECQX008056	5700	58,400	1977
ECHO	ECQX008061	5700	58,300	1977
UNIT	ECQX008063	5700	58,300	1977
UNIT	ECQX008064	5700	58,400	1977
ECHO	ECQX008066	5700	58,300	1977
SHOP	ECQX008067	5700	58,400	1977
KOSM	ECQX008070	5700	58,100	1977
UNIT	ECQX008071	5700	58,400	1977
ECHO	ECQX008078	5700	60,600	1980
ECHO	ECQX008079	5700	60,700	1980
ECHO	ECQX008083	5700	60,600	1980
ECHO	ECQX008087	5700	60,500	1980
ECHO	ECQX008090	5700	60,400	1980
ECHO	ECQX008091	5700	60,400	1980
ECHO	ECQX008093	5700	60,700	1980
UNIT	ECQX008095	5700	60,600	1980
UNIT	ECQX008098	5700	60,600	1980
UNIT	ECQX008099	5700	60,700	1980
UNIT	ECQX041381	4100	60,300	1964
UNIT	ECQX041383	4100	59,900	1964
BORG	ECQX046387	4600	62,100	1964
UNIT	ECQX046388	4600	62,100	1964
UNIT	ECQX046389	4600	61,800	1964
BRIG	ECQX046390	4600	61,700	1964
BORG	ECQX046391	4600	62,700	1966
ECHO	ECQX046392	4600	62,700	1966
BORG	ECQX046394	4600	63,300	1966
ECHO	ECQX046395	4600	62,400	1966
BORG	ECQX046396	4600	63,200	1966
BORG	ECQX046398	4600	62,400	1966
UNIT	ECQX046399	4600	62,700	1966
ECHO	ECQX046400	4600	62,900	1966
BORG	ECQX046401	4600	62,300	1966
ECHO	ECQX046402	4600	62,200	1966
BORG	ECQX046403	4600	62,300	1966

BORG	ECQX046404	4600	62,800	1966
BORG	ECQX046405	4600	62,200	1966
BORG	ECQX046406	4600	63,000	1966
BORG	ECQX046407	4600	63,000	1966
ECHO	ECQX046408	4600	63,200	1966
KOSM	ECQX046410	4600	62,600	1966
BORG	ECQX046411	4600	63,000	1966
BORG	ECQX046412	4600	62,800	1966
ECHO	ECQX046413	4600	62,500	1966
BRIG	ECQX046414	4600	62,800	1966
BORG	ECQX046415	4600	62,800	1966
UNIT	ECQX046416	4600	62,500	1966
UNIT	ECQX046417	4600	62,600	1966
ECHO	ECQX046418	4600	62,600	1966
BORG	ECQX046419	4600	63,100	1966
ECHO	ECQX046420	4600	62,100	1966
BORG	ECQX046421	4600	63,200	1966
BORG	ECQX046422	4600	62,700	1966
BORG	ECQX046423	4600	62,400	1966
shop	ECQX057424	5700	63,700	1966
BORG	ECQX057425	5700	68,100	1966
ECHO	ECQX057426	5700	59,400	1968
KOSM	ECQX057427	5700	58,800	1968
BRIG	ECQX057428	5700	59,600	1968
BORG	ECQX057429	5700	59,200	1968
BORG	ECQX057430	5700	60,700	1971
BORG	ECQX057431	5700	59,900	1971
BORG	ECQX057432	5700	60,100	1971
BORG	ECQX057433	5700	60,300	1971
ECHO	ECQX057434	5700	60,900	1971
BORG	ECQX057436	5700	59,900	1971
UNIT	ECQX057437	5700	59,700	1971
BORG	ECQX057439	5700	61,300	1971
ECHO	ECQX057440	5700	60,400	1971
ECHO	ECQX057442	5700	60,200	1971
BORG	ECQX057443	5700	59,700	1971
BORG	ECQX057444	5700	60,700	1971
BORG	ECQX057445	5700	60,500	1971
ECHO	ECQX057447	5700	60,600	1971
BORG	ECQX057448	5700	60,300	1971
ECHO	ECQX057449	5700	60,400	1971
KOSM	ECQX057450	5700	60,900	1971
SHOP	ECQX057451	5700	59,800	1971
BORG	ECQX057452	5700	60,200	1971
BORG	ECQX057453	5700	60,100	1971
KOSM	ECQX057454	5700	60,700	1971
UNIT	ECQX057455	5700	60,300	1971
SHOP	ECQX057456	5700	60,200	1971
ECHO	ECQX057457	5700	60,000	1971

BORG	ECQX057458	5700	60,000	1971
UNIT	ECQX057459	5700	60,400	1971
KOSM	ECQX057460	5700	59,800	1971
ECHO	ECQX057461	5700	60,000	1971
BORG	ECQX057462	5700	60,100	1971
BORG	ECQX057463	5700	60,600	1971
ECHO	ECQX057464	5700	60,200	1971
ECHO	ECQX057465	5700	60,700	1971
UNIT	ECQX057466	5700	60,500	1971
BORG	ECQX057467	5700	59,700	1971
ECHO	ECQX057468	5700	60,300	1971
UNIT	ECQX057469	5700	60,200	1971
ECHO	ECQX057470	5700	60,200	1971
UNIT	ECQX057471	5700	59,800	1971
BORG	ECQX057472	5700	59,500	1971
UNIT	ECQX057473	5700	60,000	1971
KOSM	ECQX057474	5700	59,500	1971
SHOP	ECQX057475	5700	60,100	1971
SHOP	ECQX057476	5700	60,000	1971
BORG	ECQX057477	5700	59,900	1971
UNIT	ECQX057478	5700	60,500	1971
ECHO	ECQX057479	5700	58,900	1971
BORG	ECQX057480	5700	60,500	1973
UNIT	ECQX057481	5700	61,100	1973
ECHO	ECQX057482	5700	61,200	1973
UNIT	ECQX057483	5700	60,800	1973
UNIT	ECQX057484	5700	60,700	1973
BORG	ECQX057485	5700	60,700	1973
UNIT	ECQX057486	5700	61,000	1973
BORG	ECQX057487	5700	60,500	1973
UNIT	ECQX057488	5700	60,500	1973
SHOP	ECQX057489	5700	60,700	1973
ECHO	ECQX057490	5700	61,400	1973
KOSM	ECQX057491	5700	61,000	1973
BORG	ECQX057492	5700	61,200	1973
BRIG	ECQX057493	5700	60,500	1973
UNIT	ECQX057494	5700	61,100	1973
unit	ECQX057495	5700	61,200	1973
ECHO	ECQX057496	5700	61,100	1973
ECHO	ECQX057497	5700	61,300	1973
KOSM	ECQX057498	5700	60,000	1973
UNIT	ECQX057499	5700	60,300	1973
UNIT	ECQX057500	5700	60,600	1973
SHOP	ECQX057501	5700	60,200	1973
UNIT	ECQX057502	5700	61,400	1973
UNIT	ECQX057503	5700	59,800	1973
KOSM	ECQX057504	5700	60,000	1973
BORG	ECQX057505	5700	60,400	1975
KOSM	ECQX057506	5700	60,400	1975

BORG	ECQX057507	5700	60,500	1975
ECHO	ECQX057508	5700	60,400	1975
SHOP	ECQX057509	5700	60,500	1975
ECHO	ECQX057510	5700	60,500	1975
UNIT	ECQX057511	5700	60,500	1975
SHOP	ECQX057512	5700	60,500	1975
UNIT	ECQX057513	5700	60,500	1975
BORG	ECQX057514	5700	60,400	1975
BORG	ECQX057515	5700	60,400	1975
SHOP	ECQX057516	5700	60,600	1975
KOSM	ECQX057517	5700	60,400	1975
BORG	ECQX057518	5700	60,500	1975
BRIG	ECQX057519	5700	60,500	1975
BORG	ECQX057520	5700	60,600	1975
BORG	ECQX057521	5700	60,500	1975
UNIT	ECQX057522	5700	60,500	1975
BORG	ECQX057523	5700	60,600	1975
BORG	ECQX057524	5700	60,400	1975
UNIT	ECQX057525	5700	60,400	1975
ECHO	ECQX057526	5700	60,800	1975
BORG	ECQX057527	5700	60,400	1975
BRIG	ECQX057528	5700	60,500	1975
BORG	ECQX057529	5700	60,500	1975
ECHO	ECQX057530	5700	61,000	1975
BORG	ECQX057531	5700	61,300	1975
UNIT	ECQX057532	5700	60,600	1975
ECHO	ECQX057533	5700	60,700	1975
ECHO	ECQX057534	5700	60,500	1975
BORG	ECQX057535	5700	58,200	1977
BORG	ECQX057536	5700	58,100	1977
shop	ECQX057537	5700	58,400	1977
KOSM	ECQX057538	5700	58,400	1977
BRIG	ECQX057539	5700	58,300	1977
BORG	ECQX057540	5700	60,400	1979
SHOP	ECQX057541	5700	60,600	1979
UNIT	ECQX057542	5700	60,400	1979
UNIT	ECQX057543	5700	60,500	1979
BORG	ECQX057544	5700	60,600	1979
BRIG	ECQX057545	5700	60,500	1979
KOSM	ECQX057546	5700	60,700	1979
ECHO	ECQX057547	5700	60,400	1979
BORG	ECQX057548	5700	60,500	1979
UNIT	ECQX057549	5700	60,600	1979
BORG	ECQX057550	5700	60,400	1979
BORG	ECQX057551	5700	60,600	1979
KOSM	ECQX057552	5700	60,400	1979
BORG	ECQX057553	5700	60,600	1979
BRIG	ECQX057554	5700	60,400	1979
ECHO	ECQX057555	5700	60,700	1979

BORG	ECQX057556	5700	60,500	1979
KOSM	ECQX057557	5700	60,700	1979
BRIG	ECQX057559	5700	60,700	1979
UNIT	ECQX057560	5700	60,400	1979
BORG	ECQX057561	5700	60,600	1979
BORG	ECQX057562	5700	60,400	1979
UNIT	ECQX057563	5700	60,500	1979
UNIT	ECQX057564	5700	60,700	1979
BORG	ECQX057565	5700	60,600	1979
BORG	ECQX057566	5700	60,500	1979
UNIT	ECQX057567	5700	60,500	1979
UNIT	ECQX057568	5700	60,500	1979
BORG	ECQX057569	5700	60,600	1979
BORG	ECQX057570	5700	60,600	1979
ECHO	ECQX057571	5700	60,700	1979
BORG	ECQX072701	7200	73,300	1969
ECHO	ECQX072702	7200	72,800	1969
ECHO	ECQX072703	7200	73,000	1969
BORG	ECQX072704	7200	73,100	1969
ECHO	ECQX072705	7200	73,400	1969
ECHO	ECQX072706	7200	72,800	1969
ECHO	ECQX072707	7200	73,300	1969
Echo	ECQX072708	7200	74,000	1969
BORG	ECQX072709	7200	72,900	1969
ECHO	ECQX072710	7200	73,000	1969
ECHO	ECQX072711	7200	73,900	1970
BORG	ECQX072712	7200	73,300	1970
ECHO	ECQX072713	7200	72,700	1970
BORG	ECQX072714	7200	73,100	1970
ECHO	ECQX072715	7200	72,300	1970
ECHO	ECQX072716	7200	72,800	1970
BORG	ECQX072717	7200	73,300	1969
BORG	ECQX072718	7200	74,800	1970
BORG	ECQX072719	7200	72,500	1970
ECHO	ECQX072720	7200	72,700	1970
BORG	ECQX072721	7200	72,900	1969
BRIG	ECQX072722	7200	72,200	1970
BORG	ECQX072723	7200	73,600	1970
BORG	ECQX072724	7200	73,100	1970
ECHO	ECQX072725	7200	72,500	1969
ECHO	ECQX072726	7200	73,300	1970
BORG	ECQX072727	7200	72,400	1970
BORG	ECQX072728	7200	74,200	1970
ECHO	ECQX072729	7200	72,400	1969
ECHO	ECQX072730	7200	74,600	1970
ECHO	ECQX072731	7200	72,800	1970
ECHO	ECQX072732	7200	72,600	1970
BORG	ECQX072733	7200	72,500	1969
BRIG	ECQX072734	7200	73,300	1970

BORG	ECQX072735	7200	72,100	1970
ECHO	ECQX072736	7200	73,000	1970
ECHO	ECQX072738	7200	73,600	1970
ECHO	ECQX072739	7200	72,600	1970
ECHO	ECQX072740	7200	72,200	1970
ECHO	ECQX072741	7200	72,600	1969