

ASSOCIATION OF AMERICAN RAILROADS 425 3rd Street, SW, Suite 1000 Washington, D.C. 20024

Timothy J. Strafford Associate General Counsel Phone: (202) 639-2506 Fax: (202) 639-2868 E-mail: tstrafford@aar.org

February 8, 2017

242595

Ms. Cynthia T. Brown Chief, Section of Administration Office of Proceedings Surface Transportation Board 395 E Street, S.W. Washington, DC 20423 ENTERED Office of Proceedings February 8, 2017 Part of Public Record

Re: EP 724 (Sub-No. 3), United States Rail Service Issues - Data Collection

Dear Ms. Brown:

Pursuant to the decision served in this proceeding on October 8, 2014, the Association of American Railroads, on behalf of its freight railroad member representatives in the Chicago Transportation Coordination Office, hereby files the attached data.

Sincerely,

Timothy J. Strafford Counsel for the Association of American Railroads

EP 724 - US RAIL SERVICE ISSUES - DATA COLLECTION

Chicago Railroad	Year: 2017	Reporting week	Date Week Began:	01/29/17	
			Date Week Ended:	02/04/17	
			NARRATIVE SUMMARY OF OPERATING CO	NDITIONS	
Chicago Gateway		Chicago Integrated Rail Operations Center (CIROC) is staffed 24/7 to monitor and facilitate rail operations.			
			th each carrier and track views to identify is	sues and assist in their resolution to	
1. Average Daily Car Counts By Terminal Yard For The Reporting Week		address congestion and reduce delays.			
Barr	2,007	 The Chicago Terminal Operating Condition (OpCon) Agreement provides the framework necessary to quickly identify and mitigate, to the degree reasonably practicable, potential and current operating conditions or events that would negatively impact rail traffic moving via the Chicago Gateway. Safety of operations is integral throughout the OpCon plan processes. The plan provides for an automated monitoring of terminal, yard, corridor and weather conditions linked to specific levels of volume/activity which could adversely impact terminal operations. These metrics, when exceeding preset levels will require predetermined countermeasures geared to effectively remove a set percentage of cars/trains from the affected location(s) in order to restore fluidity of operations. 			
Bensenville	1,022				
Blue Island	1,470				
Calumet	774				
Cicero	574				
Clearing	3,286				
Corwith	585				
Gibson	934				
Kirk	2,020	Further deterioration of the automatic indicators will require additional, predetermined, focused countermeasures			
Markham	507	geared to remove an even greater percentage of volumes to expedite a more rapid recovery, while enabling unaffected			
Proviso	2,291	areas to continue a more normal operation.			
Other Yards			itions and Individual Yard, Road or Corridor	conditions that impact operations are	
See EP 724 (Sub-No.3)		monitored and categorized separately for purposes of required countermeasures. The Operating Conditions are			
			d. Actions between railroad partners range		
2. Average Daily Number Of Trains Held For Delivery To Chicago			ic (cars and trains) to other gateways.		
ІНВ	0.00	CIROC is charged with implementation and management of the Chicago Terminal Operating Condition Agreement			
BNSF	0.00	which includes quick escalation in cases of ineffective or insufficient countermeasures. CHANGE (+/-) IN REPORTED NUMBERS: Reported numbers remained similar to last week. OPCON (ALERT LEVEL) CHANGES: There were no Elevated Levels during the report period.			
BRC	0.00				
CN	0.43				
СР	0.00				
CSX	0.00				
NS	0.14				
UP	0.00				