

ASSOCIATION OF AMERICAN RAILROADS 425 3rd Street, SW, Suite 1000 Washington, D.C. 20024

Timothy J. Strafford Associate General Counsel

Phone: (202) 639-2506 Fax: (202) 639-2868 E-mail: tstrafford@aar.org

March 4, 2015

237881

Ms. Cynthia T. Brown Chief, Section of Administration Office of Proceedings Surface Transportation Board 395 E Street, S.W. Washington, DC 20423 ENTERED Office of Proceedings March 4, 2015 Part of Public Record

Re: EP 724 (Sub-No. 3), United States Rail Service Issues - Data Collection

Dear Ms. Brown:

Pursuant to the decision served in this proceeding on October 8, 2014, the Association of American Railroads, on behalf of its freight railroad member representatives in the Chicago Transportation Coordination Office, hereby files the attached data.

Sincerely,

Timothy J. Strafford Counsel for the Association of American Railroads

EP 724 - US RAIL SERVICE ISSUES - DATA COLLECTION

Chicago Railroad	Year: 2015	Reporting week	Date Week Began:	02/22/15	
			Date Week Ended:	02/28/15	
Chicago Gateway		NARRATIVE SUMMARY OF OPERATING CONDITIONS General Summary of current CTCO service contingency protocols, including descriptions of Alert Levels			
					1. Average Daily Car Counts By Terminal Yard For The Reporting Week
Barr	1,229.3	 mitigate, to the degree reasonably practicable, potential and current operating conditions or events that would negatively impact rail traffic moving via the Chicago Gateway. Safety of operations is integral throughout the alert plan processes. The plan provides for an automated monitoring of terminal, yard, corridor and weather conditions linked to specific levels of volume/activity which could adversely impact terminal operations. These metrics, when exceeding preset levels will require predetermined countermeasures geared to effectively remove a set percentage of cars/trains from the affected location(s) in order to restore fluidity of operations. Further deterioration of the automatic indicators will require additional, predetermined, focused countermeasures geared to remove an even greater percentage of volumes to expedite a more rapid recovery, while enabling unaffected areas to continue a more normal operation. Overall Terminal Operating Conditions and Individual Yard, Road or Corridor conditions that impact operations are monitored and categorized separately for purposes of required countermeasures. The Operating Conditions are defined as Green, Yellow and Red. Actions between railroad partners range from a creation of by-pass traffic to specific diversion of Chicago traffic (cars and trains) to other gateways. CTCO is charged with development, implementation and management of the Chicago Terminal Operating Condition Agreement which includes quick escalation in cases of ineffective or insufficient countermeasures. 			
Bensenville	1,612.1				
Blue Island	1,414.3				
Calumet	608.6				
Cicero	571.9				
Clearing	3,537.9				
Corwith	810.7				
Gibson	614.9				
Kirk	1,889.4				
Markham	850.9				
Proviso	2,716.3				
Other Yards					
		which mendes quick escalation in ca	ses of memetave of misuncient countermeasures.		
2. Average Daily Number Of	0.00	CHANGE (+/-) IN REPORTED NUMBERS: Reported numbers remained similar to last week. OPCON (ALERT LEVEL) CHANGES: There were no Elevated Levels during the report period. EVENT(S) THAT AFFECTED OPERATING CONDITIONS:			
IHB	0.00				
BNSF	0.00				
BRC					
CN	1.43				
СР					
CSX	0.00	There were no Major Events affecting the Terminal.			
NS	1.14	There was no Weather Event which affected the Terminal.			
UP	0.00				