

ASSOCIATION OF AMERICAN RAILROADS 425 3rd Street, SW, Suite 1000 Washington, D.C. 20024

Timothy J. Strafford Associate General Counsel Phone: (202) 639-2506 Fax: (202) 639-2868 E-mail: tstrafford@aar.org

August 31, 2016

241409

Ms. Cynthia T. Brown Chief, Section of Administration Office of Proceedings Surface Transportation Board 395 E Street, S.W. Washington, DC 20423 ENTERED Office of Proceedings August 31, 2016 Part of Public Record

Re: EP 724 (Sub-No. 3), United States Rail Service Issues - Data Collection

Dear Ms. Brown:

Pursuant to the decision served in this proceeding on October 8, 2014, the Association of American Railroads, on behalf of its freight railroad member representatives in the Chicago Transportation Coordination Office, hereby files the attached data.

Sincerely,

Timothy J. Strafford Counsel for the Association of American Railroads

EP 724 - US RAIL SERVICE ISSUES - DATA COLLECTION

Chicago Railroad	Year: 2016	Reporting week	Date Week Began:	08/21/16
			Date Week Ended:	08/27/16
Chicago Gateway		NARRATIVE SUMMARY OF OPERATING CONDITIONS General Summary of current CTCO service contingency protocols, including descriptions of Alert Levels		
1. Average Daily Car Counts By Terminal Yard For The Reporting Week		The Chicago Terminal Operating Condition (OPCON) Agreement provides the framework necessary to quickly identify		
Barr	1,918	 and mitigate, to the degree reasonably practicable, potential and current operating conditions or events that would negatively impact rail traffic moving via the Chicago Gateway. Safety of operations is integral throughout the alert plan processes. The plan provides for an automated monitoring of terminal, yard, corridor and weather conditions linked to specific levels of volume/activity which could adversely impact terminal operations. These metrics, when exceeding preset levels will require predetermined countermeasures geared to effectively remove a set percentage of cars/trains from the affected location(s) in order to restore fluidity of operations. Further deterioration of the automatic indicators will require additional, predetermined, focused countermeasures geared to remove an even greater percentage of volumes to expedite a more rapid recovery, while enabling unaffected areas to continue a more normal operation. Overall Terminal Operating Conditions and Individual Yard, Road or Corridor conditions that impact operations are monitored and categorized separately for purposes of required countermeasures. The Operating Conditions are defined 		
Bensenville	1,080			
Blue Island	1,674			
Calumet	622			
Cicero	536			
Clearing	2,739			
Corwith	575			
Gibson	874			
Kirk	1,485			
Markham	490			
Proviso	2,008			
Other Yards			between railroad partners range from a cr	
See EP 724 (Sub-No.3)		diversion of Chicago traffic (cars ar	· · ·	eation of by-pass traine to specific
2. Average Daily Number Of Tra	ains Held For Delivery To Chicago	CTCO is charged with development	t, implementation and management of the	
IHB	0.29	Agreement which includes quick escalation in cases of ineffective or insufficient countermeasures.		

Reported numbers remained similar to last week.

0.00

0.00

0.14

0.00

0.29

0.14

0.00

BNSF

BRC

CN

СР

CSX

NS

UP

OPCON (ALERT LEVEL) CHANGES:

There were no Elevated Levels during the report period.